


- 主軸正反轉選擇鈕  
Spindle cw/ccw switch
- 進給方式選擇鈕  
Feeding mode switch
- 攻牙功能選擇鈕  
Threading function switch
- 主軸啟動按鈕  
Spindle start button
- 主軸停止按鈕  
Spindle stop button
- 主軸寸動按鈕  
Spindle inching button
- 緊急停止按鈕  
Emergency push button
- 電源開關鈕  
Power on/off button
- 切削水開關選擇鈕  
Coolant on/off switch
- 三軸油壓鎖開關  
3 Axis hydraulic clamp switch
- Z軸自動進給/快送搖桿  
Joystick for Z-axis feed and rapid
- X,Y軸自動進給/快送搖桿  
Joystick for X,Y-axis feed and rapid



► 結構堅強的機體 RIGID STRUCTURE

機身與底座為箱型結構，並採用特殊的加強肋設計，整體構造堅強、穩重，適合重力切削。

Box-shaped column and base reinforced by ribs with a strong and rigid construction which fits to do heavy cutting.